



**Recreational Equipment Substitution Request**

SITE PLAN NAME: \_\_\_\_\_ NUMBER: \_\_\_\_\_  
 SITE PLAN REVIEWER: Tamika Graham EXT. \_\_\_\_\_  
 DATE SUBMITTED: \_\_\_\_\_

Section or Phase of Development: \_\_\_\_\_  
 Name of Applicant: \_\_\_\_\_  
 Address of Applicant: \_\_\_\_\_

Authorization: I, \_\_\_\_\_, agent of the above referenced project, am requesting the substitution of the equipment specified below:

Sara Trach 9/5/23  
 Signature Date

	Previously Approved Item	Proposed Substitution
Name of Item	_____	_____
Manufacturer	_____	_____
Catalog #	_____	_____
Cost	_____	_____
Quantity	_____	_____

In the space below, justify the substitution by comparing pertinent factors affecting project quality (i.e. wood treatment, wood type, finishing, connecting system, detailing, etc). Proposed equipment should be designed for the same age group and have equivalent activities, in terms of both number and type. Attach complete specifications and cut sheets or other graphic representations for both originally specified item and proposed substitution. A print of the approved site and landscape plans showing the location and equipment list of all recreational facilities may also be required. The proposed substitution must be equal or better than the original equipment in order to be approved.

Reason for Change:

**Office Use Only:**

Disapproved: Substitution not equal or better

Comment: \_\_\_\_\_

Approved

Carrie Sanders Chief Signature 9/25/23 Date

[Signature] Supervisor Signature 9/25/23 Date

\_\_\_\_/\_\_\_\_ Date Scanned to Imageware

# Colossus Chimes Product Assessment



Percussion Play Ltd, Staple Ash Lane,  
Froxfield, Petersfield, Hampshire, GU32 1DJ



Accredited Contractor  
CHAS.co.uk

The Play Inspection Company Ltd, Unit 5 Glenmoore Business Park, Blackhill Road, Holton Heath, Poole, Dorset, BH16 6NL

t: 01202 590675

e: [info@playinspections.co.uk](mailto:info@playinspections.co.uk)

w: [www.playinspections.co.uk](http://www.playinspections.co.uk)

## Certificate of Conformity

Issue date: 6th June 2019

Percussion Play Ltd  
Staple Ash Lane  
Froxfield  
Petersfield  
Hampshire  
GU32 1DJ



### Products covered:

Colossus Chimes

The product detailed has been assessed as conforming to the main dimensional requirements of BS EN 1176:2017 based on technical drawings provided by the manufacturer

The desktop product assessments undertaken by the Play Inspection Company Ltd are not a formal certification as would be produced by an accredited test house. They are an indication of conformity based on drawings and dimensional information provided by the client.

We will check the major dimensional requirements as set out in the current standards for playground equipment (BS EN 1176- Parts 1-6, 10 & 11 as applicable to the product assessed. These dimensions include such things as barrier heights, platform heights, free height of fall, head and neck entrapment etc. but will exclude finer detail such as finger entrapment and toggle entrapments as these cannot be fully assessed based on a drawing alone. We do not undertake any structural assessment or testing, that element remains the responsibility of the designer; nor do we assess the suitability of materials used in the construction.

### Reference Standards

BS EN 1176:2017 Part 1

Assessed by: Keith Dalton

KDal ton

### The Play Inspection Company

Unit 5, Glenmore Business Park  
Blackhill Road  
Holton Heath  
Poole  
Dorset  
BH16 6NL



## Colossus Chimes Risk Assessment

Assessment Date: 10<sup>th</sup> June 2019  
Assessor: Keith Dalton  
Manufacturer: Percussion Play Ltd  
Risk Assessment: Very Low Risk



Activity: Use of musical playground equipment item

Number of Persons at Risk: Users, plus spectators

Hazards Involved with the Activity:

- | Collision
- | Entrapment

### Safety Measures/Controls:

- | All design requirements to comply fully with the requirements of BS EN 1176:2017 Part 1 incorporating, where required, criteria from all sections of the standard where it is deemed applicable to the safety of this item.
- | The challenge (risk) associated with the use of the equipment is clearly foreseeable by the users.
- | A circulation Area of 1.50 metres is recommended to allow free movement for spectators around the item without moving into the space required for the safe use of the equipment.
- | Correct siting of the equipment item within the playground environment to ensure free passage of playground users around the area.
- | Detailed inspection and maintenance procedures to be provided for the equipment providing guidance on allowable tolerances during normal operation.

Risks remaining after the application of control measures:

Collision

With all control measures applied there will still be a risk remaining of users colliding with the equipment or with other users. It is considered that this remaining risk is of no significance, or any different from similar equipment item that incorporates this type of movement.

Given the provision of the safety measures detailed the remaining risk is considered to be 1 x 2 VERY LOW RISK

Additional Controls Required:

None

Risk Rating:

Likelihood		Severity	
1	Very Unlikely	1	Minor abrasion, light bruising
2	Not Very Likely	2	Small cuts, light sprains, more severe abrasion
3	Will happen at some time	3	Deep cuts, severe sprains etc. requiring medical intervention
4	Likely to happen	4	Injury requiring medical intervention and hospitalisation
5	Almost Certain to Happen	5	Permanent disability/death

Risk Score	Description	Action Required
1 – 5	Very Low Risk	Maintain control measures
6 – 10	Low Risk	Review control measures
11 – 15	Moderate Risk	Improve control measures
16 – 20	High Risk	Prevent access to item
21 – 25	Very High Risk	Remove from site

To establish the risk score, multiply Likelihood by Severity

Controls Adequate:

Signed: KR Dalton

Date: 10<sup>th</sup> June 2019  
The Play Inspection Company Ltd  
Assessment Review Date: 10<sup>th</sup> June 2020



Colossus  
Chimes

100mm / 4"



2350mm / 93"

